



POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION

REGION SITE NUMBER

NOTE: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.

A. SITE NAME Comdaco Inc.		B. STREET (or other identifier) 3161 Wyandotte	
C. CITY Kansas City	D. STATE Missouri	E. ZIP CODE 64111	F. COUNTY NAME Jackson
G. OWNER/OPERATOR (if known) I. NAME John Comley, Owner Vern Ogan, General Manager		H. TELEPHONE NUMBER (816)756-0722	
I. TYPE OF OWNERSHIP (if known) <input type="checkbox"/> 1. FEDERAL <input type="checkbox"/> 2. STATE <input type="checkbox"/> 3. COUNTY <input type="checkbox"/> 4. MUNICIPAL <input checked="" type="checkbox"/> 5. PRIVATE <input type="checkbox"/> 6. UNKNOWN			
J. SITE DESCRIPTION Custom rubber molders and gasket cutters.			
K. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.) TSCA identified as original NESHAPs site			L. DATE IDENTIFIED (mo., day, & yr.) Unknown
M. SUMMARY OF POTENTIAL OR KNOWN PROBLEM In past, cut gaskets from sheets of rubber which contained asbestos. Possibility for an asbestos air release existed during process. Scraps were generated as waste material. Process of using asbestos in gaskets was discontinued several years ago as kevlar replaced asbestos.			
N. PREPARER INFORMATION 1. NAME David A. Tyson EAE/PIT		2. TELEPHONE NUMBER (913)432-9961	3. DATE (mo., day, & yr.) 3/24/86